

April 21, 1987

TO: File

FROM: Frank J. Filas, Reclamation Engineer



RE: Site Inspection, DOE/019/036, Rendezvous Corporation, Gold Placer

Frank Filas inspected this proposed placer site on April 13, 1987. The area can be reached by traveling southeast out of Thompson for a little over a mile. Several old trenches and gravel piles were observed on the left side of the road prior to reaching a newly staked area. This recently staked area is located just after a "Y" in the road and is situated between the two roads. It consists of a gravelly hill alongside a dry wash. No onsite disturbance was observed.

clj
1115R/83